



<section-header><list-item><list-item><list-item>









































Summary Sep04

- One can observe significant cupping of 2x4 Wedges at 2x Design Load
- Laced Post System as constructed has members and connections that are sufficient to brace system to resist 3 times Design Load
- Failure often occurs in posts w/knots that are near joints
- There is not much lateral strength or stuffiness


24































































































Sum o	of 12 L	.aced	Post Tests (w/ Diag 2x)	
Shore	Lacing	Failure	Comment	
LP-1	2x4	100k	Failed at post knots	
LP-2	2x4	90k+	Total system failure - Poor	
LP-11	2x4	90k+	Failed at post knots	
LP-12	2x4	90k+	Failed at post knots	
LP-13	2x4	N/A	Lat. load test at 38k only	
LP-21	2x6	110k+	Good performance	
LP-22	2x6	90k+	Posts were split prior to test. Failed at many joints	
LP-24	2x4	100k+	2 cycles of 2" lateral w/38k then load to failure. V.good	
LP-31	2x4	103k	New Loading Sys=accurate	
LP-41, 61	2x4	103k	Similar to LP-31	
LP-51	2x4	90k	New load frame w/no load averaging between posts 62	


63


	Sum of 12 L. Post Tests – 2x Diag
•	One can observe Significant cupping of 2x4 Wedges at 2x Working Load – Splitting of Headers may occur at 2x to 3x Working Load, depending on slope & direction of grain
	4x4 - Laced Post Systems consistently resist 3 times Working Load
	Failure often occurs in posts w/knots that are near joints
•	The Direction of the Diagonal Braces may not have a significant effect.
	The use of 2x6 Diagonals with 4x4 posts may not produce increased strength, depending on splitting of the posts due to nail concentration
	Total deflection is about 1.5 to 2" at failure


6 - LP 4'x4'Tests (w/Ply Lacing =PLP)						
Shore	Lacing	Failure	Comment			
LP-32	24"Ply	103k	Fail Sim to 2x Diag Tests			
LP-42	12"Ply	83k	Failed in Sys Buckling 12"Ply is NOT Adequate			
LP-52	24"Ply	100k	Same as LP-32			
LP-53	24"Ply	88k	Failed at poor post			
LP-62	24"Ply	115k	Closer space is ply better			
LP-63	24"Ply	144k	Ply was too close – not practical			
			64			



18-P	LP 2ft	t x 4ft ⁻	Tests w/ply lacing
Shore	Lacing	Failure	Comment (3/4"Ply UNO)
PLP-31	2-24"	88k	Failed in Elastic Buckling
PLP-32	1-24"	88k	Same – re-tested to 65k
PLP-41	2-12"	65k	Failed, buckle + posts
PLP-42	3-12"	67k	Same – 12" Ply Inadequate
PLP-51	2-24"	90k	Failed at poor post
PLP-61	4-24"	85k	Failed at poor post
PLP-62	1-96"	115k	V.good, do additional tests
PLP-71,72	1-96"	125k+	5/8"Ply V. good
PLP-73,74,81	1-96"	105k+	1/2"Ply V. good
PLP-75	1-96"	115k	3/4"OSB V. good
PLP-76	48"+24"	115k	3/4"Ply, (48" + 24" no 96")
PLP-82,83	48"+24"	115k+	PLP-82 = 5/8"ply, PLP-83 = 1/2"ply
PLP-84,85	2-24"	120k+	5/8"ply, space ply lacing near ends













73

Summary of Mar05 Crib Test
• Significant crushing can be observed when a Crib is loaded above Working Load
 Crib stability is heavily influenced by the uniformity of applied load and density of the wood at the bearings
 Cribbing give adequate warning of overload,
 Crushing is Significant
 Crushing makes easily recognized sounds Members become significantly distorted